16" Truss Connector Orientation

The connector orientation is not a problem. Truss action results in the top chord members and the bottom chord members being loaded axially.

Thus, the orientation of the connector slot is immaterial to the capacity, provided the bracing (webbing) of the truss is the same on all sides.

Tom

Thomas R. Hicks, P.E., S.E.

AHBL, Inc.